

11.0 REFERENCES

URS. 2002. In-Water Investigation Report, Bradford Island Landfill.

URS. 2002. Technical Memorandum, In-Water Removal Work, Bradford Island Landfill.

U.S. Army Corps of Engineers. 2002a. Detailed Statement of Work Contract No. DACW57-99-D-0005, URS Greiner Woodward Clyde Delivery Order No. 0004, Modification No. 0006, Bradford Island Post Removal Sampling.

U.S. Army Corps of Engineers. 2002b. Sampling and Analysis Plan, Bonneville Forebay Sediment Characterization. July 2002.

U.S. Army Corps of Engineers. 2001. Environmental Quality, Requirements for the Preparation of Sampling and Analysis Plans, EM200-1-3.

U.S. Army Corps of Engineers. 2000. First Powerhouse, Bonneville Dam, Columbia River, Oregon, Report 2, Tracking Velocities Hydraulic Model Investigation. Robert Davidson, April.

U.S. Army Corps of Engineers 1998. Navigation Conditions at Bonneville Locks and Dam, Columbia River, Ronald T. Wooley. February.

U.S. Army Corps of Engineers 1991. Bonneville Navigation Lock Sediment Evaluation, Jim Britton, September 6.

U.S.G.S. Topographic Map, 7.5 minute series, Bonneville Dam Quadrangle, Washington – Oregon, 1994.